


## OPTICAL DISC LIGHT ARM & SENSORS TOUCH: TOUCH: DISC START/STOP DISC DIRECTION

TURN: ROTATION SPEED


# <u>ORBITS</u>

INTERVALS (TUNED NOTES)



COMBINATIONS OF 0,1,2,4 SELECT TUNED NOTES 0-7

REGISTERS (OCTAVES)
AND FILTER




AT LEAST ONE REGISTER MUST BE DARKENED TO HEAR ANY SOUND FROM STAR SONG

## INTERVALS

PERMUTATIONS OF ORBITS 1, 2, 4 SELECT INTERVALS (TUNED NOTES) 0-7


## MARK DISC




BS, LH, RH, 1, 2, 4: TRACKS GATE "ON" WHEN DARKENED.

FILTER: BANDPASS, VARIABLE CUTOFF SWEEP.
DARK = LOW FREQUENCY, LIGHT = HIGH FREQUENCY

USE ONLY <u>WET ERASE</u> MARKERS AS OTHER MARKERS MAY STAIN. RE-DARKEN MARKS IF GATING IS FAILING DUE TO FADING. FOR LONGEST-LASTING MARKS, USE OPAQUE TAPE TO MARK. FOR ULTRA PRECISE GATING, MARK BACK OF DISC. WIPE TRACKS CLEAN WITH AMPLE WATER TO ERASE. FOR BEST RESULTS KEEP DISC CLEAN. DO NOT SOAK.




## TUNE A SCALE



# SIDE

INPUTS: UNIPOLAR, "ON" AT +7.5V, MAX INPUT +12V



CONNECT WAVE EXPANDER, FUTURE ACCESSORIES, OR DIY BREAKOUT BOXES.

CAT5 OR CAT6 WITH SHIELDED CONNECTOR

#### WARNINGS:

DO NOT CONNECT INPUT SOURCES UNLESS UNIT POWER IS  $\underline{\text{ON}}\,.$ 

DO NOT EXCEED +12V DC ON INPUTS.

DO NOT CONNECT NEGATIVE VOLTAGE SOURCES TO INPUTS.


AMP LINK USES ONLY CAT5 OR CAT6 W/ SHIELDED CONNECTORS

FAILURE TO HEED WARNINGS MAY RESULT IN DAMAGE.


# <u>MEMORY</u>

TITLE:

### PATTERN



#### TUNING




NOTES:	


# <u>MEMORY</u>

TITLE:

### PATTERN



#### TUNING



NOTES:	

### WWW.MELODYORACLE.COM